



Fig. 10.14 A ternary eutectic equilibrium phase diagram, displaying the solidification path for alloy x in both equilibrium and non-equilibrium solidification. Note that in the latter case, the solid composition is not constrained to pass through the nominal composition.

Copyright 2016 EPFL Press. This figure has been reproduced from *Solidification*, by J.A. Dantzig and M. Rappaz, for instructional purposes. For other uses, please contact the authors and the EPFL Press for written permission.